

## FIRST RE-ESTABLISHMENT

GCDB 200600

Corner to Sections 5, 6, 7 & 8, Township 36 South, Range 1 East, W.M.

Found original BT to Northwest, scribe visible; also original BT to Southwest, intact, from which set a 2" x 36" galvanized pipe for corner, 10" in the ground, and erected a mound of stone, 3' square at base,

From which

- The original BT a 24" white oak bears S65°W, 255.4 feet.
- Scribe a 12" white oak C.S.-BT which bears N41½°W, 195.9 feet.
- Scribe a 6" twin white oak C.S.-BT which bears N89°E, 70.9 feet.
- Scribe an 8" twin oak C.S.-BT which bears S43°E, 93.1 feet.

September 21, 1933  
P.B. Rynning, County Surveyor  
C. Z. Boyden, Deputy County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT


## SECOND RE-ESTABLISHMENT

GCDB 200600

Corner common to Sections 5, 6, 7 and 8, Township 36 South, Range 1 East, W.M.

Set a 1" x 36" galvanized iron pipe, 13" in the ground with 2½" bronze cap stamped:

T36S, R1E



From which:

- The original bearing tree, now a 24" White Oak with both blazes left intact bears S63½°W, 255.8 feet to the center of the tree.
- The original bearing tree, now an 18" White Oak snag, both faces opened and badly decayed, bears N5°W, 218.6 feet to the face of the upper blaze.

Found the following trees marked by County Surveyor P.B. Rynning on the First Re-establishment on September 21, 1933:

- A 14" White Oak, both blazes left intact bears N41½°W, 195.9 feet to the face of the upper blaze.
- A twin 7" White Oak scribed "CS" in the upper face, the lower blaze left intact bears N88½°E, 70.9 feet to the face of the upper blaze.
- A twin 10" White Oak, both blazes left intact bears S43½°E, 93.1 feet to the face of the lower blaze.

The 2" iron pipe corner monument set on said First Re-establishment could not be located. Built a mound of stone around corner and didn't scribe any new trees.

January 29, 1969  
F. Roberts, Deputy County Surveyor  
Gary Kaiser