

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 5 ONLY
GCDB 240700**

Standard Quarter corner Section 5, Township 36 South, Range 1 East.

Found anchor post and original BT to Northeast, which checks N68°00'E, 126.06 feet.

From said post:

- A 12" white oak bears N22°00'E, 45.6 feet. The standard ¼ corner for section 32 bears E. 71.28 feet.

July 29, 1926
Boyden, Deputy County Surveyor
L. E. Smith, Chainman

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

WITNESS CONRER

GCDB 240700

Standard Quarter corner on the North boundary of Section 5, Township 36 South, Range 1 East, also being on the Eighth Standard Parallel South.

The true corner falls on the North edge of an anchor post as per the First Re-establishment by Deputy County Surveyor C. Z. Boyden on July 29, 1926.

Set a 1"x36" galvanized iron pipe 27" in the ground with a 2½" bronze cap for a witness corner which bears South, 3.00 feet from the true corner. The cap is stamped:

T.36 S. R.1E.
Wit Cor. 3 feet.
C.S. 1971
South of the North
¼ Cor.
Section 5

From which witness corner with brass cap:

- A 1" galvanized iron pipe with a 2½" bronze cap located at the South quarter corner to Section 32, Township 35 South, Range 1 East, bears N87°35'30"E, 71.34 feet.
- The bearing tree to the Northeast established on the said first re-establishment by Deputy County Surveyor C. Z. Boyden (now a 16" White Oak in good condition with the "BT" scribed visible) bears N21°E, 48.4 feet to the face of the lower blaze; (this tree bears N 22¼° E, 45.6 feet from the true corner (First re-establishment: 12" White Oak N22°E, 45.6 feet.)

Mark new trees as follows:

- A 19" Black Oak scribed "CS-BT" bears S43¼°W, 85.4 feet to the face of the lower blaze, from said witness corner.

January 19, 1971
Gary Kaiser, Deputy County Surveyor
Lloyd Shreeve