

FIRST RE-ESTABLISHMENT

GCDB 300340

Quarter corner common to Sections 20 and 21, Township 36 South, Range 1 East, W.M.

Found broken down mound of stone partially buried with a very rusty spike 1 ins. square and 12 ins. long. Replaced spike with a 1x36 ins. galvanized iron pipe 30 ins. in the ground with a 2½ ins. diam. brass cap marked:

T36S R1E
¼S
20 | 21
C.S.
1994

- Remaining original bearing tree recorded by Ives and Hyde in 1854 found;
- Rotted Oak stump remains brs. N50°29'W, 129.20 feet to center. Record; N54°W, 121.44 feet (184 lks.). Found that 194 lks. fits better.

Marked new trees "CS" "BT" and take measurements to center of tree at lower blaze:

- White Oak 9 ins. diam., brs. N49°41'E, 23.23 feet.
- White Oak 8 ins. diam., brs. N73°10'W, 43.59 feet.

Set a concrete nail in a basalt rock outcropping 1 feet high and 58" x 58" brs. S42°36'20"W, 31.30 feet.

Section corner brs. North 2646.89 feet ±. Center East one-sixteenth brs. N89°10'55"W, 1334.58 feet. Record; N89°53'W, 1332.80 feet.

Corner lies 2 feet east of north-south fence line.

March 14, 1994
T. Newcomb, Tech.
J. Hawkinson, Tech.

Verlyn Thomas
County Surveyor

P.-40