

## FIRST RESTABLISHMENT

GCDB 340600

Quarter corner to Sections 4 and 9, Township 36 South, Range 1 East, W.M.

Found the 1" x 24" galvanized iron pipe set by Surveyor A.T. Brown over 40 years ago and a stump hole to agree with the original witness tree which bears S75°W, 202.6 feet. This corner location falls at the intersection of old rail fences to the South and West.

From said pipe corner (the top of which is 2" above the ground surface):

- Scribed a 9" White Oak "CS-BT" which bears N74°E, 171.0 feet.
- Scribed an 8" White Oak "CS-BT" which bears N58½°W, 115.4 feet.

April 9, 1957  
C. Z. Boyden  
K. D. Weaver

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 340600

Quarter corner common to Sections 4 and 9, Township 36 South, Range 1 East, W.M.

At the corner, found flush with the ground, in a ring of stone, the 1 ins. diam. iron pipe reported on first re-establishment, in 1957. In the top of said pipe, set a 2½ ins. diam. bronze disc marked:

JACKSON COUNTY 1982  
T36S R1E  
4  
¼S —  
9

Bearing trees marked on first re-establishment found as follows:

- White Oak, 13 ins. diam., with healed blazes, brs. Record: N74°E, 171.0 feet to estimated face. Re-measured, 171.57 feet to center of tree at lower blaze.
- White Oak, 12 ins. diam., with healed blazes, brs. N58°25'W, 115.74 feet to center of tree at lower blaze. Record; N58½°W, 115.4 feet.

Corner lies alongside the (metal) post corner of north and east bearing fence lines.

October 20, 1982

R. Frost

R. Templin

Edward McGinty

County Surveyor

V = 21°

P.-152