

FIRST RE-ESTABLISHMENT

CORNER COMMON TO SECTIONS 2 AND 3 ONLY

GCDB 500700

Standard corner common to Sections 2 and 3, Township 36 South, Range 1 East on the South boundary of Section 34, Township 35 South, Range 1 East.

Found all four original bearing trees.

For corner, set a 1" x 36" galvanized iron pipe, 30" in the ground with bronze cap stamped:

T35 & 36S, R1E
3 4
Sec ——— Cor.
3 | 2
c.s.
1963

From which:

- The original bearing tree (now a 30" White Oak with good relief scribe) bears North $26\frac{1}{2}^\circ$ East, 120.8 feet;
- The original bearing tree (now a 30" White Oak snag) bears North 5° West, 133.8 feet;
- The original bearing tree (now a 36" Black Oak with rotted face) bears South $16\frac{1}{2}^\circ$ East, 181.6 feet (record = South $15\frac{1}{2}^\circ$ East, 178.86 feet).
- The original bearing tree (now a stump hole with down pine) bears South 63° West, 133.7 feet.

From said pipe corner, I establish the following new witness trees:

- Scribed a 24" Yellow Pine, "CS-BT" which bears North $44\frac{1}{2}^\circ$ West, 21.3 feet to the face of the upper blaze;
- Scribed a 15" White Oak, "CS-BT" which bears South $82\frac{1}{4}^\circ$ West, 85.2 feet to the face of the upper blaze;
- Scribed a 12" White Oak, "CS-BT" which bears South $15\frac{1}{2}^\circ$ West, 115.7 feet to the face of the upper blaze;
- The 1" iron pipe with bronze cap located at the closing corner common to Section 34 & 35, T35S, R1E, bears North 89° East, 66.77 feet.

November 14, 1963
F. A. Roberts
Lloyd Hart

Approved by:
Mark E. Boyden
County Surveyor