

FIRST RE-ESTABLISHMENT

GCDB 600400

Section corner common to Sections 13, 14, 23 and 24, Township 36 South, Range 1 East, W.M.

From the following original evidence, at the location described below, set a 1x36 ins. galvanized iron pipe, for the corner, 26 ins. in the ground with a 2½ ins. diam. brass cap marked:

T36S R1E	
14	13

23	24
C.S.	
1983	

From which, original bearing trees recorded by Ives and Hyde in 1854, found as follows:

- Black Oak, now 16 ins. diam. with rotted out upper face, brs. Record: S69°E, 77.22 feet (on slope) to estimated face. Re-measured 74.96 feet to center of tree at upper blaze.
- The shell of a Black Oak snag, 26 ins. diam. with rotted out upper face, brs. Record: S20°W, 67.32 feet to estimated face.
- Stump hole containing Pine fragments with Pine section alongside scribed "S-14" brs. N32°W, 34.5 feet to center.
- Original Northeast BT is now gone.

Mound stones around corner, marked new trees "CS" "BT" and take measurements to center of tree at lower blaze:

- White Oak, 5 ins. diam., brs. N62°E, 38.45 feet.
- Ponderosa Pine, 14 ins. diam., brs. S51°E, 19.25 feet.
- Black Oak, 6 ins. diam., brs. S24°W, 22.32 feet.
- Ponderosa Pine, 21 ins. diam., brs. N42°W, 47.50 feet.

Corner lies on East slope along the Northwest side of the wood post corner of South and East bearing fence lines.

April 13, 1983
R. Frost
R. Templin
Witness: V. Gardener

Edward McGinty
County Surveyor

P.-35