

FIRST RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13-14, Township 36 South, Range 1 East.

- Original bearing tree a White Oak in Section 13 in place.
- Bearing tree in Section 14 destroyed.
- A 1" gas pipe set for corner according to the field notes from which a new bearing tree, a 16" white oak scribed S. C. S. bearing tree bears S.71¼°W, 128.3 feet

This ¼ corner is about 5 feet south of irrigation ditch and about 10 feet from south bank of Little Butte Creek.

A. T. Brown, Deputy County Surveyor
H. Berian, Chainman
July 28, 1914

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 600440

Quarter corner common to Sections 13 and 14, Township 36 South, Range 1 East, W.M.

From the following evidence, set a 1x36 ins. galvanized iron pipe 28 ins. in the ground. In the top of said pipe, set in concrete, a 2½ ins. diam. brass cap marked:

T36S R1E
¼S
14 | 13
C.S.
1988

Original bearing tree marked by Ives and Hyde in 1854 found:

- White Oak, now 16 ins. diam., down with axed faces found in opened blazes, brs. Record: N77°E, 37.6 feet to estimated position of original face in stump hole.

Bearing tree marked on first re-establishment, page 2, in 1914 found:

- White Oak, now 17 ins. diam. with single healed blaze, brs. Record: S71¼°W, 128.3 feet to center of tree at root crown.
- The South bank of an irrigation ditch bears North, 5.0 feet.

Scribe a new tree CS BT:

- Ponderosa Pine, 17 ins. diam., brs. S52½°E, 14.80 feet to center of tree at lower blaze.

Corner lies 2.0 feet East of the former position of a fallen, 20 ins. diam. Pine corner post to fences bearing South and East. Little Butte Creek is now North an estimated 300 feet. The mouth of a southerly bearing draw brs. West, 85 feet.

February 25, 1988
D. Edwards, Tech.
T. Newcomb, Tech.

Edward McGinty
County Surveyor

V = 16¼°

P. - 68