

## FIRST RE-ESTABLISHMENT

GCDB 640100

Quarter corner on Township line common to Section 36, Township 36 South, Range 1 East and Section 1, Township 37 South, Range 1 East.

Found the Yellow Pine bearing tree intact with 2 scars visible, also the black oak snag down by the stump hole. Opened the oak snag and found "¼S" scribe.

For corner, set a 1"x36" galvanized iron pipe 30" in the ground with 2½" bronze cap stamped:

T36 & 37S, R1E  
36  
¼S — c.s.  
cor1  
1964

From which:

- The center of said original pine bearing tree bears South 35° East, 24.5 feet;
- The center of the stump hole of the original black oak bearing tree bears North 65° East, 28.9 feet.

From said pipe corner, I establish an additional witness tree, to wit:

- A 10" Cedar scribed "CS-BT" bears North 17½° East, 41.3 feet to the face of the lower blaze.

April 23, 1964  
L. D. Pinkham  
Lloyd Hart  
Vic Gardner, present

Mark E. Boyden  
County Surveyor