

FIRST RE-ESTABLISHMENT

GCDB 100340

Quarter corner common to Section 24, Township 36 South, Range 2 East and Section 19, Township 36 South, Range 3 East, W.M.

Found at the bottom of a mound of stone, a pipe hole with a 1x12 ins. iron pipe with BLM brass cap marked:

¼
S24 | S19

1956

Lying alongside.

In said pipe hole, set a 2½x32 ins. galvanized iron pipe with 2½ ins. diam. brass cap marked:

T36S
¼S
R2E 24 | 19 R3E
C.S.
1987

3 ins. in the ground to refusal and rebuild mound of stone.

Original bearing trees marked by Ives and Hyde in 1854 found:

- Black Oak, now 30 ins. diam. with scribing including "¼" found inside hollow, open top, bears N76°E, 152.1 feet to center of tree near base. Record: N81°E, 153.1 feet.
- White Oak, now 23 ins. diam. with rotted face areas, bears Record: S8°W, (base bearing) 113.7 feet to center of tree near base. Record distance; 116.2 feet.

Bearing trees marked on 1956 BLM restoration found:

- Cedar, now 19 ins. diam. with single healed blaze, bears 88¾°E, 227.7 feet to center of tree near base. Record: S89¼°E, 228.4 feet.
- Cedar, now 43 ins. diam. with single healed blaze, bears N57°W, 146.6 feet to center of tree near base. Record: N56°W, 145.2 feet.

Corner lies on 35% southerly slope in a large rocky opening.

May 27, 1987
D. Edwards, Tech II
T. Newcomb, Tech I

Edward McGinty
County Surveyor

P.-165