

FIRST RE-ESTABLISHMENT

GCDB 100600

Section corner common to Sections 1 and 12 of Township 36 South, Range 2 East, and Sections 6 and 7 of Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962 and marked:

T36S
R2E R3E
S1 | S6
—+—
S12 | S7
1962

Single remaining original bearing tree recorded by Ives and Hyde of the GLO in 1884 found and measured to center at base;

- W. Fir high stump brs. record N77°E, 13.2 ft.

Bearing trees recorded by the BLM in 1962 found with Healed single blazes and measured to center at base;

- W. fir now 25 ins. diam. brs. record S49°E, 69.3 ft.
- W. fir now 20 ins. diam. brs. record N66°W, 17.2 ft.
- W. fir high stump with a partially healed single blaze with scribe 'T36SR3E S6 BT' brs. record N58½°E, 52.8 ft.
- Bearing stone 'BXO' not found, rock broken, brs. record S63½°W, 6.6 ft. top point of rock outcrop brs. S46°E, 7.7 ft.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- W. fir 17 ins. diam. brs. N57°E, 15.8 ft.

Corner lies approx. 350 ft. north-easterly from end of spur road.

November 2, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -247

V. - 16°30'