

FIRST RE-ESTABLISHMENT
ANGLE POINT
GCDB 143700

SPECIAL CORNER

Angle Point between Sections 31 of Township 35 South, and Section 6 of Township 36 South, Range 3 East, W.M.

Found at the proportioned corner position, exposed 4 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1963 and marked:

T35S R3E
S31
AP—
S6
1963

Bearing trees recorded by the BLM in 1963 found with healed single blazes and measured to center at base;

- Cedar now 12 ins. diam. with a partially healed blaze with scribe 'T35S R3E S31 BT' brs. N16½°W, 35.4 ft. record; 35.0 ft.
- W. fir high stump brs. S29½°W, 19.1 ft. record; S31½°W.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- Chinquapin 6 ins. diam. brs. N10¾°E, 21.5 ft.
- Cedar north-easterly fork 9 ins. diam. brs. S14°W, 7.4 ft.
- No available trees in south-east quadrant

Corner lies approx. N45°E, 400 ft. of spur road.

November 9, 2009

B. Beeman
H. Durkee

Kerry K. Bradshaw
Jackson County Surveyor

P. – 252
V. – 14°45'