

## FIRST RE-ESTABLISHMENT

GCDB 200140

Quarter corner common to Sections 31 and 32, Township 36 South, Range 3 East, W.M.

Found the original SE witness tree and stump hole of the original NW Witness tree. Also found the original corner stone dislodged from its original position.

Set a 1" x 36" galvanized iron pipe with brass cap stamped:

T36S R3E  
¼Cor 31 | 32 C.S.  
1960

For corner.

From which:

- The original witness tree (now a 28" Black Oak plainly scribed "¼S - BT") bears South 72°East, 38.3 feet.
- The center of the original witness tree with bark ring evident bears North 59° West, 66.0 feet.

I mark new trees as follows:

- A 7" Cedar, scribed "CS-BT" bears North 79°E, 8.0 feet.
- A 16" Black Oak, scribed "CS-BT" bears S81°W, 35.5 feet.

October 12, 1960  
L. D. Pinkham  
C. L. Birk

Approved by:  
Mark E. Boyden  
Deputy County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

GCDB 200140

Quarter corner common to Sections 31 and 32, Township 36 South, Range 3 East, W.M.

Found at the corner, projecting 6 ins., the 1 ins. diam. galvanized iron pipe, with 2½ ins. diam. brass cap marked:

T36S R3E  
¼ Cor 31 | 32 C.S.  
US BLM  
1962  
1960

Set on First Re-establishment, page 3, in 1960. The original 15 x 8 x 6 ins. stone is found, marked "¼" among stones mounded around corner.

The single remaining original bearing tree recorded by R. Moore in 1883, now a tipped over Black Oak, about 26 ins. diam., containing scribe marks in burned faces, the face of which bears Record: S72°E, 38.3 feet.

Bearing trees marked on First Re-establishment:

- Burned Cedar snag, 8 ins. diam., with scribe marks visible on partly healed over faces, bears Record: N79°E, 8.0 feet to face. Re-measured 8.4 feet to center of base.
- Black Oak (alive but fire damaged) 16 ins. diam., leaning Westerly, bears S82°W, 35.5 feet to estimated upper face. Re-measured 35.5 feet to center at base. Record: S81°W.

Bearing trees marked by BLM in 1962:

- Base of down and burned Cedar, 8 ins. diam., bears Record: N19°W 3.63 feet.
- The stump, 8 ins. diam., of down and burned Fir, containing scribe marks including "¼s", bears Record: S49°E, 20.46 feet to center.

Mk. new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- The Southwest branch, 12 ins. diam. of a forked Cedar bears N35°15'E, 51.10 feet.
- Cedar, 15 ins. diam., bears N77°00'W, 67.5 feet.

Corner lies about 500 feet North of location marker on 3 ins. diam. Madrone, located at top of cut bank to Highway No. 140.

May 6, 1982  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

V = 19°  
P. -65

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

### THIRD RE-ESTABLISHMENT

GCDB 200140

Quarter corner common to sections 31 and 32, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins. and in a mound of stones, the 1 in. diam. galvanized iron pipe with a 2½ ins. diam. brass cap, set on First Re-establishment in 1960, marked:

T36S R3E  
¼ COR 31 ↓ 32 C.S.  
US BLM  
1962  
1960

Single remaining bearing tree recorded on said First Re-establishment in 1960, a charred oak stump bears Record: S 82° W, 35.5 feet to center of stump.

Bearing trees recorded on Second Re-establishment in 1982 found charred by fire but alive and healthy.

- Southwesterly branch of forked cedar, now 15 ins. diam. with healed double blazes bears Record: N 35¼° E, 51.1 feet to center of tree at lower blaze.
- Cedar, now 17 ins. diam. with partially healed upper blaze revealing scribe marks "CS" bears N 77° W, 67.1 feet. Record: 67.5 feet to center of tree at lower blaze.

Take new reference, a 5/8 x 24 ins. rebar with a 1½ ins. diam. bronze cap, exposed 3 ins. and marked:

JACKSON COUNTY  
  
SURVEYOR

Brs. S 82° W, 33.9 feet.

No trees available and very rocky in southeast quadrant.

Corner lies approximately 500 feet north of Highway 140 in patch of small, burnt madrone trees.

February 7, 2006  
H. Durkee

Roger R. Roberts  
Jackson County Surveyor

P. - 18  
V. - 17°15'