

FIRST RE-ESTABLISHMENT

GCDB 200440

Quarter corner common to Sections 17 and 18, Township 36 South, Range 3 East, W.M.

Found tipped over, the 20 x 17 x 9 ins. original stone set by R. Moore in 1883, marked "¼".

I replace said stone with a galvanized iron pipe, 1 ins. diam., 36 ins. long, set 34 ins. in the ground (pipe leans 20° South of vertical) with a 2½ ins. diam. brass cap marked:

"T36S R3E"
¼S
18 | 17
C.S.
1981

For the corner.

- An original bearing tree now a sawed fir stump, 42 ins. diam., with felled tree alongside containing scribed "BT" in exposed section of lower blaze, bears Record: N75°W, 56.76 feet, to visible portion of lower face in said stump.

Reference trees marked on Survey No. 3664 in 1968 found:

- Douglas Fir, 13 ins. diam., with scribe marks visible in partly healed single blaze, bears S58°E, 15.75 feet to center of tree; Record 16.2 feet.
- White Fir, 10 ins. diam., with scribe marks visible in partly healed single blaze, bears N18°W, 8.10 feet to center of tree; Record N16°W, 8.0 feet.

Mound stones around corner, deposit original stone alongside and mark a new tree "CS" "BT":

- Douglas Fir, 20 ins. diam., bears S74°W, 38.28 feet to center of tree at lower blaze.

Corner lies on South slope, 10 feet West of North-South fence line.

January 7, 1981

R. Frost

R. Templin

Witness: T. Newcomb USFS

Edward McGinty

County Surveyor

V = 19°

P. -5