

FIRST RE-ESTABLISHMENT

GCDB 200640

Quarter corner common to Sections 5 and 6 of Township 36 South, Range 3 East, W.M.

Found at corner position exposed 6 ins. with original stone alongside, the 2½ ins. diam. galvanized iron pipe with a 2½ ins. diam. brass cap set on Survey No. 8345 in 1980 and marked:

T36S R3E
¼
S6 + S5
1979
LS 1086

Bearing trees recorded by Art Rambo in 1980 found:

- Pine now dead, down and rotted bears Record: S51¼°E, 18.4 feet to center on stump hole.
- Fir now 19 ins. diam. with healed double blazes bears Record: S57°W, 17.0 to center at lower blaze.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- Douglas Fir 7 ins. diam. bears S61¼°E, 20.4 feet.
- Douglas Fir 6 ins. diam. bears N35¼°W, 21.9 feet.
- Cedar 15 ins. diam. bears N20°E, 13.3 feet.

Corner lies approximately 620 feet S75°E of end of spur road and 1 foot west of north-south fence-line.

November 5, 2007

B. Beeman

H. Durkee

Roger R. Roberts

Jackson County Surveyor

P. - 240

V. - 15°50'