

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 5 AND 6 ONLY
GCDB 200700**

Closing corner common to Sections 5 and 6 of Township 36 South Range 3 East, closing on Section 32, Township 35 South Range 3 East, W.M.

Found at the corner position, exposed 8ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1963 and marked:

T35S R3E	
S32	
S6	S5
T36S	R3E
C	C
1963	

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883 found and measured to center at base;

- Fir weathered stob brs. S25°W, 12.5 ft. record; 8.6 ft.

Bearing trees recorded by the BLM in 1963 found with healed single blazes;

- W. fir now 16 ins. diam. brs. record; S25½°E, 37.6 ft.
- W. fir dead, down, and rotted brs. record; S35°W, 31.4 ft. to center of stump hole.

Marked new bearing trees 'CS''BT' and measured to center at lower blaze;

- D. fir 9 ins. diam. brs. S57¾°W, 17.7 ft.

Corner lies approx. 700 ft. north of old logging road and 3.5 ft. north of southerly and westerly bearing fence corner.

November 10, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. -255

V. - 16°15'