

FIRST RE-ESTABLISHMENT

ANGLE POINT

GCDB 203700

Angle point common to Section 32 of Township 35 South, and Section 5 of Township 36 South, Range 3 East, W.M.

Found at corner position, exposed 6 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1963 and marked:

AP
T35S R3E
S32
——
S5
T36S
1963

Aluminum post with sign 1.5 ft. west.

Bearing trees recorded by the BLM in 1963 found;

- W. fir dead, down, and rotted brs. record; N60°W, 42.9 ft. to center of stump hole.
- W. fir now 15 ins. diam. with a healed single blaze, brs S20½°W, 30.7 ft. record; 31.0 ft. to center at base.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 10 ins. diam. brs. N55½°W, 18.3 ft.
- D. fir 8 ins. diam. brs. N36°E, 14.4 ft.
- Chinquapin 9 ins. diam. brs. S37°E, 7.1 ft.

Corner lies approx. 700 ft. north of old logging road.

November 10, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

P. – 254