

FIRST RE-ESTABLISHMENT  
GCDB 240300

SPECIAL CORNER

Quarter corner common to Sections 20 and 29 of Township 36 South, Range 3 East, W.M.

Found at proportioned corner position exposed 7 ins., the 1 in. diam. galv. iron pipe with a 2½ ins. diam. brass cap set by the BLM in 1956 and marked:

S20  
—— ¼  
S29  
1956

Bearing trees recorded by the BLM in 1956 found with healed single blazes and measured to center at base;

- D. fir now 34 ins. diam. brs. record N36°E, 27.1 ft.
- D. fir now 34 ins. diam. brs. record S84½°E, 25.1 ft.

Marked new bearing tree "CS" "BT" and measured to center at lower blaze:

- Chinquapin 17 ins. diam. brs. S18¾°W, 22.0 ft.
- No other suitable trees within limits in the North-West quadrant

Corner lies approx. 450 ft. east from end of spur road.

June 16, 2009

B. Beeman

H. Durkee

Kerry K. Bradshaw

Jackson County Surveyor

P. – 129

V – 16°25'