

FIRST RE-ESTABLISHMENT

GCDB 300600

Section corner common to Sections 4, 5, 8 and 9, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T36S R3E
S5 | S4
—+—
S8 | S9
1966

Original bearing trees recorded by R. Moore of the GLO in 1883, found with healed blazes and measured to center at base:

- W. Fir, now 23 ins. diam., brs. N44°E, 4.0 ft. record; N21°E.
- W. Fir snag brs. record; S40°E, 28.4 ft.

Bearing trees recorded by the BLM in 1966, found with healed single blazes and measured to center at base:

- Fir, dead, down and dislodged, brs. record; N44°E, 37.0 ft. to center of stump hole.
- W. Fir, now 24 ins. diam. brs. record; S60°E, 24.4 ft.
- W. Fir snag brs. N33½°W, 23.8 ft. Record; N35°W.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 7 ins. diam. brs. N8¼°W, 29.4 ft.
- W. Fir 5 ins. diam. brs. S25°W, 17.2 ft.

Corner lies approx. 750 ft. east of gravel logging road near top of ridge.

January 30, 2012

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 125

V. – 16°10'