

FIRST RE-ESTABLISHMENT

ANGLE POINT

GCDB 303700

Angle Point between Section 33, Township 35 South, Range 3 East and Section 4, Township 36 South, Range 3 East, W.M. $V = 17\frac{1}{2}^\circ$, 42 lks. East of C.C. 4 and 5 (T36S)

In 1883, R. Moore perpetuated N. Ford's 1855 "Standard Corner" to Section 4 and 5 (T36S) and marked new reference trees.

The single remaining tree found, is now a burned and rotted Fir stump, about 34 ins. diam., with section alongside containing scribed "T3" and "E" in old axe faces.

From the preceding evidence:

I set a 1 x 36 ins. G.I. pipe 32 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1975
T35S R3E
S 33
A.P.
S 4
T36S

From which:

- The above-described BT bears record, N16°E, 31.68 feet to estimated lower face.

I mound stones around corner, marked the following trees C.S. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 10 ins. diam., bears S24°E, 21.18 feet.
- Cedar, 14 ins. diam., bears N59°W, 34.39 feet.

The closing corner of Section 4 and 5 (See 1973 C.S. re-establishment, pg. 4), bears record (R. Moore, 1883) West, 27.72 feet.

Note: This corner referred to by Moore in 1883 as the S.C. of Section 32 and 33. See second re-establishment N¼ corner Section 2, T36S, R3E.

November 10, 1975
R. Frost
T. Newcomb, USFS

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

ANGLE POINT

GCDB 303700

Angle Point between Section 33, Township 35 South, Range 3 East and Section 4, Township 36 South, Range 3 East, W.M.

Fd. the 3½ ins. BLM brass cap in mound of stone mkd:

AP
T35S R3E
S 33

S 4
T36S
1977

Bearing trees mkd on 1975 First Re-Establishment found with healed blazes and measured to center of trees at base:

- Cedar, 22 ins. diam. brs. BLM Record N58°W, 34.39 ft. (basis of bearing). 1975 Record N59°W.
- Douglas Fir, 18 ins. diam., brs. S22°03'40"E, 20.38 ft.; Record, S24°E, 21.18 ft.

Bearing tree reported in 1977 by the BLM, is the BT for the Closing Corner marked on the First Re-establishment for the Closing Corner in 1973:

- Fir, 22 ins. diam. brs. S15°12'33"W 76.55 ft.; BLM Record, S14°W, 75.24 ft. BT found with healed blaze oriented toward the Closing Corner and not remarked.

Fd. Closing Corner for T36S R3E, Sections 4 and 5 as established in 1973 by the Jackson County Surveyor's Office and noted on previous Re-Establishment:

- 2½ ins. diam. brass cap mkd:

T35S
CLOS COR
S5 | S4
T36S R3E
1973

Brs. N88°17'43" W, 28.07 ft; Record, West, 27.72 ft.

Corner lies in strip of wooded land between two gravel forest roads that fork approximately 80 northwest of corner.

Note: This corner referred to by Moore in 1883 as the S.C. of Section 32 and 33. See second re-establishment N¼ corner Section 2, T36S, R3E.

July 27, 2017
B. Paull
J. Hall

Scott Fein
County Surveyor

P-