

FIRST RE-ESTABLISHMENT

GCDB 340500

Quarter corner common to Sections 9 and 16, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 9 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T36S R3E
S9
¼—
S16
1962

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883, a down and rotted Fir, brs. record; S59°W, 11.2 ft. to center of stump hole.

Bearing trees recorded by the BLM in 1962, found with healed single blazes and measured to center at base:

- D. Fir, now 20 ins. diam. brs. record; N64°E, 8.6 ft.
- D. Fir, now 24 ins. diam. brs. record; S32°W, 42.2 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- D. Fir 9 ins. diam. brs. N40¾°W, 23.9 ft.
- W. Fir 12 ins. diam. brs. S45°E, 31.0 ft.

Corner lies approx. 250 ft. east of logging road and approx. 100 ft. west of drainage on a blazed line.

October 27, 2010

H. Durkee

Kerry Bradshaw
Jackson County Surveyor

P. – 213

V. – 15°30'