

FIRST RE-ESTABLISHMENT

GCDB 400440

Quarter corner common to Sections 15 and 16, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 12 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T36S R3E
¼
S16 | S15
1962

Single remaining original bearing tree recorded by R. Moore of the GLO in 1883

- A rotted Fir sawed stump, brs. record; N66°W, 9.2 ft. to estimate face.

Bearing trees recorded by the BLM in 1962, found with healed single blazes and measured to center at base:

- S. Pine, dead and down, brs. record; N33°E, 17.2 ft. to center of root hole.
- Fir high-stump 14 ins. diam. brs. record; S78°W, 10.9 ft.

Bearing tree recorded on Survey No. 9537 in 1983

- A chinquapin high-stump 10 ins. diam. with scribe marks "¼ S 15" and "BT" in partially healed double blazes and a brass washer with "L.S. 1086" nailed to lower blaze, brs. record; S35°E, 30.2 ft. to center at base.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 12 ins. diam. brs. N28°W, 11.5 ft.
- D. Fir 5 ins. diam. brs. N34°E, 13.8 ft.
- No other trees practical due to clear-cut.

August 13, 2012

H. Durkee

Scott Fein
Deputy County Surveyor

P. – 26

V. – 16°