

## FIRST RE-ESTABLISHMENT

GCDB 400500

Section Corner common to Sections 9, 10, 15 and 16, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 12 ins. in a large mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962, marked:

T36S R3E	
S9	S10
S16	S15
1962	

Bearing trees recorded by the BLM in 1962, found with healed single blazes and measured to center at base:

- D. Fir high-stump brs. S54°E, 7.9 ft. record; S51°E.
- Sawed Fir stump brs. record; S61°W, 30.4 ft.
- Sawed Fir stump brs. Record; N26°W, 39.6 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Cedar 6 ins. diam. brs. west, 13.4 ft.
- W. Fir 9 ins. diam. brs. N41°W, 31.5 ft.
- Chinquapin 7 ins. diam. brs. N51¾°E, 15.6 ft.
- No trees of size in southeast quadrant.

Corner lies in clear cut approx. 200 ft. north of logging road.

October 27, 2010

H. Durkee

Kerry Bradshaw  
Jackson County Surveyor

P. – 212

V. – 14°50'