

**FIRST RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 3 AND 4 ONLY
GCDB 400700**

Re-establishment of closing corner to Sections 3 and 4, Township 36 South, Range 3 East.

Found remains of old hub with nail set by myself for corner in 1930.

From the scribed fir to the Southwest, scribed Chinquapin to the Southeast and a stump hole to Northeast.

- Chinquapin is at present a burnt snag, but the Fir to the Southwest, although down, still has the scribing plainly legible and the stump hole to the Northeast still remains, all of which evidence verifies the location of the hub.

Set a 2" x 24" iron pipe 22" in the ground for corner from which:

- A 46" Fir, scribed CS-BT bears South 12°E, 10.7 feet.
- A 28" Fir, scribed CS-BT bears North 71°E, 61.6 feet.
- A 34" Fir, scribed CS-BT bears North 58°W, 58.6 feet.

Note: The standard corner to Sections 4 and 3 as set by Ford in 1855 bears Easterly 59.4 feet as determined by the Southeast BT, down but scribing legible.

June 21, 1950
C. Z. Boyden
L. D. Pinkham
M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

**SECOND RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 3 AND 4 ONLY
GCDB 400700**

Closing corner common to Section 3 and 4, Township 36 South, Range 3 East, W.M. $V = 21\frac{3}{4}^\circ$

Found, tipped over, the 2 x 24 ins. iron pipe set on First re-establishment by C. Z. Boyden in 1950.

I replace said pipe with a 1 x 36 ins. G.I. pipe set 30 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1975
T35S

4 | 3
C.C.
T36S R3E

From which bearing trees recorded by Boyden found as follows:

- Fir stump, 36 ins. diam., scribed "BT" in exposed face, bears record N71°E, 61.6 feet to scribed face.
- Fir stump, 42 ins. diam., scribed "BT" and partial "S" in exposed faces, bears record S12°E, 10.7 feet to scribed lower face.
- The stump hole of tipped out Fir, 36 ins. diam., bears record N58°W, 58.6 feet.

I deposit found pipe alongside corner, marked new trees C.S. BT and take measurements to center of trees at lower blaze:

- Douglas Fir, 8 ins. diam., bears N23°E, 13.0 feet.
- Douglas Fir, 8 ins. diam., bears S12¼°E, 63.19 feet.
- Cedar, 7 ins. diam., bears S47°W, 17.48 feet.

The corner (angle point) of Section 33 and 34 bears S88½°E, 59.4 feet (See index J, Book A-1 on file for C. Z. Boyden, 1930 field notes) as recorded by Boyden in 1950.

Corner lies 42 feet East of creek. A metal fence post stands on East side of corner.

November 13, 1975
R. Frost
T. Newcomb, USFS

Approved by: Edward McGinty
County Surveyor

SEE NEXT PAGE FOR THIRD RE-ESTABLISHMENT

**THIRD RE-ESTABLISHMENT
CORNER COMMON TO SECTIONS 3 AND 4 ONLY
GCDB 400700**

Closing corner common to Section 3 and 4, Township 36 South, Range 3 East, W.M.

Found, 2½ ins. bronze disc set on the Second Re-establishment, dated 1975, marked:

Jackson County 1975
T35S

4 | 3
C.C.
T36S R3E

From which bearing trees mkd. On the First Re-establishment, dated 1950, found and recorded in 1975:

- Fir stump, 36 ins. diameter the NE bearing tree badly rotted and not remeasured.
- Fir stump, 42 ins. diameter, with exposed lower face, brs. record S12°E, 10.7 feet to scribed lower face, 12.38 ft. to center of stump.

Found trees mkd in 1975 with healed blazes and measured to center of tree at base:

- Douglas Fir, 18 ins. diameter, brs. N19°28'09"E, 12.62 ft; Record, N23°E, 13.0 ft.
- Douglas Fir, 12 ins. diameter, found dead and down. Root hole brs. S12°05'26"E, 63.91 ft.; Record, S12¼°E, 63.19 ft.
- Cedar, 14 ins. diameter, brs. S47°22'25"W, 17.35 ft; Record S47°W, 17.48 ft.

New Reference taken:

- 2½ ins. diam. brass cap set at angle point in 1975 mkd:

Jackson County 1975
T35S R3E
S 34
A.P.
S 3
T36S

Brs. Record S88½°E, 59.40 ft. (BASIS OF BEARING)

Corner lies 42 ft. East of creek and approximately 50 ft. South of logging road.

July 21, 2017
B. Paull

Scott D. Fein
Jackson County Surveyor

P.