

**FIRST RE-ESTABLISHMENT**


**GCDB 420120**

V = 16°

Southwest One Sixteenth corner located in Section 34 of Township 36 South Range 3 East, W.M.

Found 2½ ins. diam. galvanized iron pipe protruding 3 ins. above ground level, pipe bent slightly to the East, the brass cap is missing. Monument was set on Filed Survey 8783 dated 1981.

Straighten found pipe and set a 2 ins. diam. brass cap, in top in cement marked;



From which bearing trees marked in 1981 found;

- Incense Cedar 21 ins. diam. with healed blaze brs. N48¼°W, 53.50 ft. to center of tree at base. Record bearing S48°18'E.
- Ponderosa Pine 20 ins. diam. with healed blaze brs. S88°E, 91.50 ft. to center of tree at base. Record bearing S77°52'W.

Corner is located 8 ft. South of entrance wall and along east side of landscape retaining wall. Residence 24015 Highway 140.

November 1, 2012  
S. Beecher  
S. Fein

Scott Fein  
Deputy County Surveyor

P. - 6  
Series II Book I