

FIRST RE-ESTABLISHMENT

WITNESS POINT

GCDB 423700

Re-establishment of Witness Point No. 2 to the Standard Quarter Corner, Section 3, Township 36 South, Range 3 East, W.M.

The Bureau of Land Management conducted a Dependent Resurvey in 1977 in which no evidence was found for C. Z. Boyden's iron pipe set at the true corner, nor either of the two witness corners set as noted on first re-establishment, dated 1950. At the **proportionate distance** of witness corner two position, the BLM established a new monument, which was found as follows:

A 3 ins. diam. brass cap set by the BLM in 1977 for Witness Point No. 2, mkd:

WP
T35S R3E
S 34

S 3
T36S
1977

From which bearing tree with healed blaze reported on 1977 BLM survey, measured to center of tree at base:

- Fir, 13 ins. diam. brs. Record N12° E, 46.20 ft (70 lks).

New tree marked "CS" "BT" and measured to center of tree at lower blaze:

- Fir, 14 ins. diam. brs. S44½°E, 34.38 ft.

Monument is located on level area, approximately 110 ft. west of asphalt road, in wooded area, just north of campground. BLM record from the Witness Point to the Standard Quarter Corner of Sec. 3, T36S R3E is S88°22'E, 630.3 feet (9.55 Chs.).

July 20, 2017
B.Paull
J. Hall

Scott D. Fein
Jackson County Surveyor

V = 14°
P. -

Note: This re-establishment was formerly included as the Second Re-establishment to T363E 440700.