

FIRST RE-ESTABLISHMENT

GCDB 440700

Re-establishment and Witnessing Standard $\frac{1}{4}$ Corner, Sections 3, Township 36 South, Range 3 East, W.M.

Set a 1" x 36" galvanized iron pipe for corner from the original Pine BT to the Northwest reported by R.S. Moore, 1883.

This corner falls in proposed reservoir site, so it was witness and referenced as follows:

- North $88^{\circ}26'45''W$, 450.0 feet (on line to the standard section corner, sections 3 and 4).

From said $\frac{1}{4}$ corner set a 1 x 1 x 24 ins. square iron pin flush with the ground From which:

- A 9" Cedar scribed CS-WC-1-BT bears $N49\frac{1}{4}^{\circ}W$, 14.35
- A 7" Cedar scribed CS-WC-1-BT bears $N23\frac{1}{2}^{\circ}E$, 6.6 feet.
- A 14" Sugar Pine scribed CS-WC-1-BT bears $S5\frac{1}{2}^{\circ}E$, 30.2 feet.

Also from said iron pin a 1" x 24" iron pin bears $N88^{\circ}26'45''$ West, 180.0 feet.

From which:

- A 6" Fir scribed CS-WC-2-BT bears $S78\frac{1}{4}^{\circ}E$, 29.3 feet.
- A 6" Fir scribed CS-WC-w-BT bears $N27^{\circ}E$, 24.6 feet.
- A 6" Fir scribed CS-WC-2-BT bears $S21^{\circ}W$, 16.2 feet.

(See map)

August 15, 1950
C. Z. Boyden
L. D. Pinkham
M. E. Boyden

Note: Second Re-establishment, previously posted in error, now removed. - 08/03/2021