

FIRST RE-ESTABLISHMENT

GCDB 500240

Quarter corner common to Sections 26 and 27 of Township 36 South, Range 3 East, W.M.

Found at corner position , exposed 12 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1962 and marked:

T36SR3E
¼
S27 | S26
1962

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883 found with a healed blaze and measured to center at base;

- P. pine high stump brs. record; S31°W, 18.5 ft.

Bearing trees recorded by the BLM in 1962 found with healed single blazes and measures to center at base;

- Cedar now 18 ins. diam. brs. S65½°E, 26.4 ft. record; S64°E.
- D. fir high stump brs. record; S69°W, 40.3 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- D. fir 16 ins. diam. brs. S51½°W, 86.3 ft.
- D. fir 14 ins. diam. brs. N43½°E, 25.0 ft.

No trees within limits in north-west quadrant.

Corner lies approx. 300 ft east of gravel spur road, and approx 50 ft. east of closed spur road.

December 9, 2009

B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 268
V. – 15°15'