

FIRST RE-ESTABLISHMENT

GCDB 500640

Re-establishment and Witnessing Standard Section Corner, Sections 2 and 3, Township 36 South, Range 3 East, W.M.

Set a 2" x 34" galvanized iron pipe for corner from the original Cedar BT to the Northeast reported by R.S. Moore, 1883.

This corner falls in proposed reservoir, so it was witnessed and referenced as follows:

- South $88^{\circ}38'45''$ East, 275.0 feet (on line to the standard $\frac{1}{4}$ corner to Section 2) from said corner set a 1 x 1 x 24 ins. square iron pine flush with the surface of the ground From which:
- A 7" Fir scribed CS-WC-1-BT bears $N11^{\circ}30'W$, 59.4 feet.
- A 10" Fir scribed CS-WC-1-BT bears $N82\frac{3}{4}^{\circ}W$, 11.25 feet.
- A 14" Fir scribed CS-WC-1-BT bears $S26\frac{3}{4}^{\circ}E$, 49.5 feet.

Also from said iron pin, a 1" x 24" iron pin bears $S88^{\circ}38'45''E$, 225.0 feet from which:

- A 4" Black Oak scribed CS-WC-2-BT bears $N79^{\circ}E$, 4.6 feet.
- A 4" Black Oak scribed CS-WC-2-BT bears $S24^{\circ}W$, 17.0 feet.
- A 4" Black Oak scribed CS-WC-2-BT bears $N24\frac{3}{4}^{\circ}E$, 26.15 feet.

(See map)

August 14, 1950
C. Z. Boyden
L. D. Pinkham
M. E. Boyden