

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 2 ONLY
GCDB 540700**

Re-establishment of Standard North $\frac{1}{4}$ Section corner, Section 2, Township 36 South, Range 3 East, W.M.

Found Surveyor Ford's original Black Oak, BT to Southeast dead with scribe legible. No other evidence, from which BT

- Set a 1" x 24" iron pipe flush with the ground on record course and distance from the said original BT.

From which corner:

- A 6" Black Oak scribed CS-BT bears North 78° East, 32.3 feet;
- Scribed a 6" Cedar "CS-BT" which bears South 71° West, 14.9 feet.

August 14, 1950
C. Z. Boyden
L. D. Pinkham
M. E. Boyden

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 540700

Point described by C. Z. Boyden in 1950 as the standard North $\frac{1}{4}$ Section corner, Section 2, Township 36 South, Range 3 East, in page 1 of the re-establishment notes.

An intensive review of the original survey of the Eighth Standard Parallel between T35S, R3E and T36S, R3E as run by Nathaniel Ford in 1855 and the subsequent retracement by Rufus Moore in 1883 was made.

Ford ran the Parallel East from the standard corner of T36S, R2 & 3E, setting standard $\frac{1}{4}$ corners and section corners for the North boundary of T36S R3E.

Upon setting the N.E. corner T36S R3E and standard corner to Section 1 and 6, he returned to the point of beginning and ran the West boundary of T35S R3E, the North boundary of T35S R3E and closed, intersecting the 8th Standard Parallel, 344 lks. West of Standard corner to Section 1 and 6, T36S R3 and 4 East.

According to his notes he then ran a true line for the East boundary of T35S R3E North from the closing corner of 36 and 31. He then returned to the S.E. corner of the township, on the 8th Standard Parallel, and began the subdivision of the township during which he set $\frac{1}{4}$ corners and closing section corners for T35S R3E on the 8th Standard Parallel.

Rufus Moore in 1883 re-ran the 8th Standard Parallel. He commenced at the corner to Twps. 35 South, Ranges 3 and 4 East and ran West setting a standard $\frac{1}{4}$ corners at 40 chains. At 80.82 chains he calls for the corner to Section 35 and 36 as found and re-monuments said as the standard corner common to Section 35 and 36, T35S R3E. He continues West erroneously re-monumenting those corners set by N. Ford for the standard corners to T36S, R3E as the standard corners to T35S, R3E.

Moore then is subdividing T36S R3E establishing closing corners on the Standard Parallel. The standard corners set by Ford for the twp. to the South thus lost their identities except as angle points.

As a result the point re-established was erroneously called the standard North $\frac{1}{4}$ section corner, section 2, T36S, R3E by C. Z. Boyden. In actuality it is an angle point common to Section 35, T35S R3E and Section 2, T36S R3E, W.M.

At said angle point I found a 1 ins. diam. iron pipe flush with the ground.

From which:

- The stob of the Black Oak marked by N. Ford in 1855 now 18 ins. diam., and 60 ins. high, containing a scribed "4" and backward "S" in open upper face and reversed B and 1/ lying alongside, bears record S45°E, 42.8 feet to face of upper blaze.
- Found Incense Cedar, marked by C. Z. Boyden in First re-establishment 1950, now 7 ins. diam., with healed blazes, bears record S71°W, 15.0 feet to center.

SECOND RE-ESTABLISHMENT CONTINUED ON NEXT PAGE

SECOND RE-ESTABLISHMENT (Continued)

GCDB 540700

- Also found the dead and down remains of the Black Oak, now 6 ins. diam., marked by C. Z. Boyden with CS scribed in open upper face, this tree apparently pushed from its original position by a tractor.
- A stump depression was found at the record location of R. Moore's BT, however there exists no remains of N. Fords S.W. BT.

I marked a new tree C.S. BT, a Douglas Fir, 8 ins. diam., bears N33 $\frac{3}{4}$ °W, 17.7 feet to center at lower blaze.

November 12, 1975
K. Weaver
T. Newcomb, USFS

Approved by: Edward McGinty
County Surveyor