

FIRST RE-ESTABLISHMENT

GCDB 600300

Section corner common to Sections 23, 24, 25, and 26 of Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 14 ins., in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T36SR3E
S23 | S24
—+—
S26 | S25
1966

Single remaining original bearing tree recorded by Rufus Moore of the GLO in 1883 found with a healed blaze and measured to center at base;

- D. fir now 28 ins. diam. brs. record; S37°E, 20.5 ft.

Bearing trees recorded by the BLM in 1966 found with healed single blazes and measured to center at base;

- D. fir high stump brs. record; N6°E, 48.8 ft.
- P. pine still 26 ins. diam. brs. record; S3°E, 43.6 ft.
- D. fir now 13 ins. diam. brs. record; S33°W, 12.5 ft.
- D. fir now 18 ins. diam. brs. record; N29°W, 15.8 ft.

Marked new bearing tree 'CS''BT' and measured to center at lower blaze;

- Cedar 5 ins. diam. brs. N71°E, 8.9 ft.

Corner lies approx. 200 ft north of felled 36 ins. diam. cedar used to block road.

December 3, 2009

B. Beeman

Kerry K. Bradshaw
Jackson County Surveyor

P. – 267

V. – 15°45'