

## FIRST RE-ESTABLISHMENT

GCDB 640100

Quarter corner common to Section 36 of Township 36 South, and Section 1 of Township 37 South, Range 3 East, W.M.

Found at corner position, exposed 2 ins., the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966 and marked:

T36SR3E  
S36  
— ¼  
S1  
T37S  
1966

Steel post with sign approx. 1 ft. south.

Original bearing trees recorded by William Turner of the GLO in 1883 found with healed blazes and measured to center at base;

- Y. pine high stump brs. N53°W, 15.7 ft.; record 13.9 ft.
- Y. pine now 37 ins. diam. brs. S20½°E, 18.9 ft.; record S23°E, 17.8 ft.

Bearing trees recorded by the BLM in 1966 found and measured to center at base;

- W. fir high stump with partially healed double blaze with scribe '1/4 S' 'BT' brs. N24½°E, 10.6 ft.; record N26°E, 11.2 ft.
- D. fir 16 ins. diam. brs. record S48°E, 21.1 ft.

Marked new bearing trees "CS" "BT" and measured to center at lower blaze:

- W. fir 6 ins. diam. brs. N64½°E, 15.2 ft.
- Cedar 9 ins. diam. brs. S60½°W, 18.3 ft.

No trees within limits in the North-West quadrant

Corner lies approx. 2850 ft. easterly along blocked spur road, then approx. 50 ft. south.

July 14, 2009

B. Beeman

Kerry K. Bradshaw  
Jackson County Surveyor

P. – 146

V. – 16°30'