

**FIRST RE-ESTABLISHMENT  
QUARTER CORNER TO SECTION 25 ONLY  
GCDB 700240**

East quarter corner of Section 25, Township 36 South, Range 3 East, W.M.

Found at the corner position, exposed 6 ins. in a mound of stones, the 2½ ins. diam. galv. iron pipe with a 3½ ins. diam. brass cap set by the BLM in 1966, marked:

T36S  
R3E  
¼ S25 |  
1966

Original bearing trees recorded by L. E. Wilkes of the GLO in 1925, found and measured to center at base:

- Sawed, rotted Fir stump, brs. record; S42½°W, 36.3 ft.
- W. Fir snag, 32 ins. diam. with healed double blazes, brs. record; N38°W, 55.4 ft.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- W. Fir 9 ins. diam. brs. N39¾°W, 12.5 ft.
- D. Fir 6 ins. diam. brs. S79¼°W, 64.3 ft.

Corner lies approx. 2100 ft. north from end of logging spur road.

December 10, 2012  
H. Durkee

Scott Fein  
Jackson County Surveyor

P. – 87  
V. – 14°40'