

**FIRST RE-ESTABLISHMENT
QUARTER CORNER TO SECTION 24 ONLY
GCDB 700340**

Quarter corner common to Section 24 only, Township 36 South, Range 3 East, W.M.

Found at the corner position, protruding 6 ins. and in a ring of stones, the 3½ ins. diam. brass cap recorded by L. Wilkes of the GLO in 1925.

- Single remaining bearing tree recorded by Wilkes in 1925, a fir snag, now 30 ins. diam. with opened, rotted upper blaze and healed lower blaze bears S33°W, 25.6 feet to center at lower blaze. Record: S31°W, 24.42 feet to face.
- A fir, down and rotted bears S60°W, 55.4 feet to center of stump hole. Record: S61°W.
- A pine, now a sawed stump, could not be measured due to down trees and brush. Record: N16°W, 126.06 feet.

Mark new bearing trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Douglas Fir, 7 ins. diam. bears S73°W, 97.7 feet.
- Douglas Fir, 12 ins. diam. bears N60°W, 29.0 feet.
- BLM brass cap monument for ¼ corner of Section 19 only, Township 36 South, R4E, W.M. bears S6½°W, 15.74 feet

Corner lies approximately 350 feet westerly of graveled spur road.

May 9, 2005
H. Durkee

Roger R. Roberts
Jackson County Surveyor

P. - 49
V. - 15°