

FIRST RE-ESTABLISHMENT

GCDB 700500

Section corner common to Sections 12 and 13 only, Township 36 South, Range 3 East, and Section 7, Township 36 South, Range 4 East, W.M.

At the corner, found projecting 6 ins. in mound of stone, 2 ins. diam. iron pipe with 3 ins. diam. standard BLM brass cap marked:

T36S
R3E R4E
S12 |
———| S7
S13 |
1962

With original stone lying alongside.

Bearing trees reported by the BLM in 1962 found:

- Original bearing tree recorded by R. Moore in 1883; now a down Cedar (wind fall) 24 ins. diam., the base of which bears Record: S74°W, 17.82 feet.
- Douglas Fir marked in 1925 (Wilkes); now 32 ins. diam. with healed single blaze, bears N10°W, 27.60 feet to center. Record: 27.06 feet.

Bearing trees marked by BLM in 1962 found:

- Fir snag, now 21 ins. diam., scribed "T36S R3E S13BT" in exposed single face, bears Record: S6°W, 58.74 feet to center.
- Fir, 19 ins. diam., with healed single blaze, now down (windfall) the base of which bears Record: N69°W, 46.20 feet to center.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Cedar, 8 ins. diam., bears N66°E, 51.75 feet.
- Douglas Fir, 9 ins. diam., bears S40°W, 68.40 feet.

Corner lies 32 feet East of road c. N-S.

March 29, 1983
R. Frost
R. Templin

Edward McGinty
County Surveyor

V = 19°