

## FIRST RE-ESTABLISHMENT

GCDB 100200

Section corner common to Sections 30 and 31, Township 36 South, Range 4 West and Sections 25 and 36, Township 36 South, Range 5 West, W.M.

At the corner, found firmly set, 18 ins. in the ground, the 12 x 12 x 36 ins. stone, marked with 5 grooves on the North and 1 groove on the South side, by H. Perkins on 1905 corner restoration. Said stone marked also with cross on top. Replace found stone with a  $\frac{5}{8}$  x 12 ins. rebar flush with yellow plastic cap marked:

JACKSON CO.  
C.S.

Remaining bearing trees recorded in 1905 found:

- Madrone, 15 ins. diam., axed and/or rotted out in area of faces, brs. N42°E, 6.40 feet to center of tree at estimated upper face. Record; 6.60 feet.
- Douglas Fir, 23 ins. diam., with healed blazes brs. Record: N65°W, 15.18 feet to center.

A reference tree, not of record:

- Douglas Fir, 25 ins. diam., with healed single blaze, brs. S48½°W, 43.20 feet.

Deposit found stone alongside corner, mk. new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- White Oak, 9 ins. diam., brs. N47°E, 44.65 feet.
- Black Oak, 5 ins. diam., brs. S70°E, 13.60 feet.

Corner lies on Southeast slope, about 1500 feet West of Savage Creek Road.

September 15, 1983  
R. Frost  
R. Templin

Edward McGinty  
County Surveyor

V = 17°  
P.-98

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

## SECOND RE-ESTABLISHMENT

### GCDB 100200

Section corner common to Sections 30 and 31, Township 36 South, Range 4 West and Sections 25 and 36, Township 36 South, Range 5 West, W.M.

Found flush, the  $\frac{5}{8}$  x 12 ins. rebar replacing the original stone as found on first re-establishment dated 1983. Yellow plastic cap missing. Replaced rebar with a 1x30 ins. flanged galvanized iron pipe 24 ins. in the ground, with attached 2½ ins. brass cap marked:

T36S	
25	30
36	31
R5W R4W	
1993	
JACKSON COUNTY SURVEYOR	

Original bearing trees recorded by Ives and Hyde in 1854 found:

- Douglas Fir, 29 ins. diam., with healed blazes, brs. S76°E, 54.78 feet slope distance. Record; S71°E. Horizontal distance, 50.58 feet.
- Oak stump hole with oak remains and scribe marks "BT" and chaining notch brs. S83°W, 35.64 feet. Record; S72°W.

Bearing trees recorded by H.C. Perkins in 1905 found:

- Madrone, 16 ins. with rotted single face, brs. Record: N42°E, 6.60 feet to estimated face. Tree is leaning East. Bearing and distance to where tree leaves the ground brs. N35°E, 6.00 feet to center at base.
- Douglas Fir, 23 ins. diam. with single healed blaze, brs. Record: N65°W, 15.18 feet to estimated face.

Bearing tree of which there is no Record: a Douglas Fir, 24 ins. diam., with healed single blaze, brs. S49½°W, 43.20 feet to center of tree at base. Record (1983); S48½°W.

Corner lies on southeast slope, about 1500 feet West of savage Creek Road.

October 19, 1993  
T. Newcomb, Tech.  
J. Hawkinson, Tech.

Verlyn Thomas  
County Surveyor

V = 17°  
P.-152