

FIRST RE-ESTABLISHMENT

GCDB 100440

Quarter corner common to Sections 18, Township 36 South, Range 4 West and Section 13, Township 36 South, Range 5 West, W.M.

From the following original evidence, at the location described below, set a 1 x 36 ins. galvanized iron pipe, 30 ins. in the ground. In the top of said pipe, set in concrete, a 2½ ins. diam. brass cap marked:

T36S
R5W R4W
¼S
13 | 18
C.S.
1986

Bearing trees marked by Ives and Hyde in 1854 found:

- Stump hole of a down pine, approximately 30 ins. diam., with burned upper face visible, brs. Record: S54°E, 44.22 feet to estimated position of said face.
- Fir snag, now 48 ins. diam. with scribed "S" visible in opened upper face, brs. Record: N41°W, 50.82 feet to said face.

Bearing tree marked on Survey No. 1327 found:

- Fir, now 24 ins. diam. with single healed blaze, brs. S14°E, 45.80 feet to center of tree at root crown.

Marked new tree "CS" "BT":

- Fir, 21 ins. diam. brs. S58°W, 43.07 feet to center of tree at lower blaze.
- A 1½ ins. diam. iron pipe set on Survey No. 1327, found loosely set in a broken mound of stones, brs. S44½°E, 7.0 feet.

Corner lies on a 38% East slope, an est. 60 feet West of a switchback on a North-South jeep road.

November 18, 1986
T. Newcomb
D. Edwards

Edward McGinty
County Surveyor

V = 17°
P. -316