

FIRST RE-ESTABLISHMENT

GCDB 140700

Quarter corner common to Section 31, Township 35 South, Range 4 West and Section 6, Township 36 South, Range 4 West, W.M.

At the corner found a 3" squared wood post set by BLM on a 1985 administrative survey. Replaced post with a 1x36 ins. galvanized iron pipe set 27 ins. in the ground, with a 2½ ins. brass cap marked:

T35S R4W
31
¼S —
6
C.S.
T36S
1992

Original bearing trees recorded by Ives and Hyde in 1854 found:

- Black Oak, 21 ins. diam. with sawed and axed out face with remains of reverse impression of face and partial scribe marks "<" laying on the ground, brs. Record: S17°W, 21.12 feet to estimated face.
- Stump hole brs. Record: N18½°E, 31.65 feet to estimated face.

Marked new trees "CS" "BT" and take measurements to the center of tree at lower blaze:

- Douglas fir, 13 ins. diam., brs. N40°W, 19.40 feet.
- Douglas fir, 13 ins. diam., brs. S58¾°W, 38.75 feet.
- Black Oak, 11 ins. diam., brs. S19½°E, 29.75 feet.
- Black Oak, 5 ins. diam., brs. N44°E, 17.95 feet.

Fence line projecting east and west is tied to the northeast bearing tree.

April 8, 1992
T. Newcomb, Tech.
H. Durkee, Tech.

Verlyn Thomas
County Surveyor

V = 19°
P.-12