


**FIRST RE-ESTABLISHMENT**

**GCDB 200200**

Corner common to Sections 29, 30, 32 and 31, Township 36 South, Range 4 West, W.M.

Found 2 ins. deep, the 3/4x13 ins. iron pipe reported found on Survey No. 985 in 1957. Replace said pipe with a 1x36 ins. galvanized iron pipe set 38 ins. in the ground. In the top of said pipe, set in concrete, a 2½ ins. diam. brass cap marked:



Scribe trees "CS" "BT" and measure to center of trees at lower blaze:

- White Oak, 11 ins. diam., brs. N43¾°E, 52.60 feet.
- White Oak, 11 ins. diam., brs. S23¾°E, 15.40 feet.
- White Oak, 13 ins. diam., brs. S24¾°W, 17.94 feet.
- Black Oak, 23 ins. diam. with saw hole, brs. N61°W, 31.66 feet.

Corner lies 2.5 feet Southwesterly from the middle of dirt road, course N38°W, and at the Easterly side of an opening.

September 21, 1988  
D. Edwards, Tech.  
T. Newcomb, Tech.

Edward McGinty  
County Surveyor


V = 18¼°  
P. -345

**NOTE:**

See commissioners Journal Vol. 14, Pg. 418 for information about found iron pipe. TLN 1989

**ADDENDUM:**

Corner damaged by State Forestry cut work during fire on June 28, 1994. Replaced damaged pipe and brass cap with a 1x36 ins. diam. galvanized iron pipe set 39 ins. in the ground with a 2½ ins. diam. brass cap marked:



August 2, 1994  
T. Newcomb, Tech.  
J. Burgess, Tech.