

FIRST RE-ESTABLISHMENT

GCDB 200240

Quarter corner common to Sections 29 and 30, Township 36 South, Range 4 West.

Found original BT to Southeast with scribe visible, also original BT to Northwest damaged by fire.

From which evidence set a 1"x36" galvanized iron pipe 33" in the ground for corner.

- Scribed a 6" White Oak CS-BT which bears North $66\frac{1}{4}^{\circ}$ East, 28.4 feet;
- Scribed a 20" Black Oak CS-BT which bears South 6° East, 84.0 feet.

October 23, 1937

C. Z Boyden

C. I. Bourne

C. S. Hatch

C. Carpenter } Present

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 200240

Quarter corner common to Sections 29 and 30, Township 36 South, Range 4 West, W.M.

At the corner, found 1 in. diam. iron pipe, projecting 2 ins. set of First re-establishment, page 10, in 1937. In the top of said pipe, set in cement, a 2½ ins. diam. brass cap marked:

T36S R4W
¼S
30 | 29
C.S.
1982

Original bearing trees recorded by Ives & Hyde in 1854 found:

- Black Oak, 32 ins. diam., with axed out upper face, brs. Record: S9°E, 53.46 feet to estimated original face position. Re-measured, 54.00 feet to center of tree.
- Black Oak stump, now 30 ins. diam. and rotted, brs. N13°W, 63.0 feet to center. Record; 62.04 feet.

Bearing trees marked on First re-establishment, page 10, in 1937 found:

- White Oak, 15 ins. diam. with healed blazes, brs. Record; N66°15'E, 28.4 feet to estimated face. Re-measured 28.57 feet to center of tree.
- Black Oak, 29 ins. diam. with healed blazes, brs. Record S6°E, 84.0 feet to estimated face. Re-measured, 84.76 feet to center of tree.

Mk a new tree "CS BT":

- Ponderosa Pine, 11 ins. diam., brs. N74°30'W, 84.12 feet to center of tree at lower blaze.

Corner lies 9 feet West of center of gravel road at gateway.

March 10, 1982
R. Frost
R. Templin

Edward McGinty
County Surveyor

P. -32