

FIRST RE-ESTABLISHMENT

GCDB 200440

Quarter corner common to Sections 17 and 18, Township 36 South, Range 4 West, W.M.

Found 1½ ins. iron pipe extending 6 ins. marked "RS 404", set on Survey No. 1834 in 1961.
Replaced said 1½" pipe with 1x36 ins. galvanized iron pipe 30 ins. in the ground with 2½ ins. brass cap marked:

T36S R4W
¼S
18 | 17
C.S.
1989

Original bearing trees recorded by Ives and Hyde in 1854 found:

- Cedar, 29 ins. diam. with healed blazes bears Record: N1°E, 31.68 feet. Re-measured 32.10 feet to center of tree at lower blaze.
- Fir stub dead and down bears Record: S62°W, 15.18 feet to est. face.

Bearing tree per Survey No. 1834 in 1961 found and measured to center tree at lower blaze:

- Madrone, 15 ins. diam., bark scribed, bears N89°W, 17.37 feet to center of tree at lower blaze. Record: S88¼°W, 16.50 feet.

Marked new trees "CS" "BT" and take measurements to center of tree at lower blaze:

- Douglas Fir, 5 ins. diam., S59½°W, 7.70 feet.
- Douglas Fir, 6 ins. diam., N8¼°E, 19.08 feet.

Corner lies on Easterly slope, South about 35 feet to center of road.

January 20, 1989
H. Durkee, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 19°
P. -30

ALSO SEE RECORDED SURVEY NO. 1327