

FIRST RE-ESTABLISHMENT

GCDB 200640

Quarter corner common to Sections 5 and 6, Twp. 36 South, Range 4 West, W.M. $V = 18^\circ$

Found, in a mound of stone, 2 ins. diam., black-iron pipe, projecting 2 ins., near corner of North and West bearing fence lines. See survey No. 1833, dated 1961.

Inside said 2 ins. pipe I set a 1x36 ins. G.I. pipe 30 ins. in the ground with a 2½ ins. bronze disc marked:

Jackson County 1975
T36S R4W
5
¼S —
6

- An original BT, recorded by C. J. Howard in 1883, a Black Oak, now 18 ins. diam., with chopped out face alongside containing reverse impression of scribe marks, including "4", bears record N76°E, 42.90 feet to estimated face of upper blaze.
- A large stump hole found at record location of original S.W. BT.

I marked new trees C. S. BT and take measurements to center of trees at lower blaze:

- A Douglas Fir, 11 ins. diam., bears S81°E, 23.16 feet.
- A Douglas Fir, 12 ins. diam., bears S34°W, 32.45 feet.

Corner lies about 700 feet South of road. Afore-mentioned fence corner bears N45°E, 4.0 feet.

March 24, 1975

B. Malotte

R. Frost

Approved by: Edward McGinty
County Surveyor