

GCDB 200700

Corner common to Sections 5 and 6, Township 36 South, Range 4 West and Sections 31 and 32,
Township 35 South, Range 4 West, W.M.

See Survey No. 1833

SEE NEXT PAGE FOR FIRST RE-ESTABLISHMENT

FIRST RE-ESTABLISHMENT

GCDB 200700

Section corner common to Sections 31 and 32, Township 35 South, Range 4 West and Sections 5 and 6, Township 36 South, Range 4 West.

Found a 2" iron pipe, exposed 3", as set on Recorded Survey No. 1833,

From which:

- Original, now 20" White Oak with faces rotted and no scribe, bears North 11° West, 36.3 feet;
- Original, now 18" Black Oak badly burned and no scribe, bears North 42¾° East, 51.5 feet;
- Found rotted pine stump which bears South 47° West, 21.5 feet to center of stump;
- Found stump hole to Southeast.

Scribe new trees as follows:

- An 8" Fir, scribed "CS-BT" bears South 42° West, 23.3 feet to the face of the upper blaze;
- A 9" Fir, scribed "CS-BT" bears South 36° East, 42.9 feet to the face of the upper blaze;
- A 10" Fir, scribed "CS-BT" bears North 33° West, 29.8 feet to the face of the lower blaze;
- A 9" Sugar Pine, scribed "CS-BT" bears North 27° East, 26.8 feet to the face of the lower blaze.

Quarter corner common to Section 5 and 31 bears East, 2664.0 feet.

January 5, 1967

G. Kaiser

G. Nygren

Approved By:

L D. Pinkham

Deputy County Surveyor