

FIRST RE-ESTABLISHMENT

GCDB 300100

Section corner common to Sections 32 and 33, Township 36 South, Range 4 West and Sections 4 and 5, Township 37 South, Range 4 West, W.M.

Found at the corner, projecting 3 ins., a $\frac{5}{8}$ x 30 ins. rebar with a yellow plastic cap pounded over the top, (origin unknown).

From the following original evidence at the location described below, set a 1 x 36 ins. galvanized iron pipe, 31 ins. in the ground. In the top of said pipe, set in concrete, a $2\frac{1}{2}$ ins. diam. brass cap marked:

T36S R4W	
32	33

5	4
T37S	
C.S.	
1986	

Original bearing trees marked by Ives and Hyde in 1854 found:

- Center of a stump hole of a down White Oak, now 28 ins. diam. with BLM bearing tree tag attached, brs. Record: N25°E, 80.4 feet.
- Center of a stump hole of a down Black Oak, now 30 ins. diam. with opened rotted faces, in which a fragment of reverse impression scribing in the BT scribe was found, brs. Record: S21°E, 73.9 feet.
- Center of a stump hole of a down 40 ins. diam. Black Oak brs. Record: S6°W, 61.1 feet.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Fir, 9 ins. diam. brs. N23°E, 17.40 feet.
- Fir, 5 ins. diam. brs. S30½°E, 8.35 feet.
- Fir, 4 ins. diam. brs. S5°W, 17.20 feet.
- Black Oak, 9 ins. diam. brs. N49¼°W, 19.03 feet.

Corner lies in a wooded area, on a 55% Southeasterly slope, an estimated 100 feet North of a draw, course East.

November 14, 1986
D. Edwards
T. Newcomb

Edward McGinty
County Surveyor

V = 18½°

P. -311