

FIRST RE-ESTABLISHMENT

GCDB 300500

Section corner common to Sections 8, 9, 16 and 17, Township 36 South, Range 4 West, W.M.

Found projecting 8 ins., the 2 ins. diam. iron pipe set on Survey No. 1834 in 1961. In top of said pipe set a 2½ ins. diam. brass cap marked:

T36S R4W	
8	9
— —	
17	16
C.S.	
1989	

Original bearing trees recorded by Ives and Hyde, in 1854 found:

- Black Oak, now 21 ins. diam. with double healed blazes brs. record S63°W, 62.04 feet to estimated face. Re-measured 62.35 feet to center of tree at base.
- Old chopping in Black Oak stump hole brs. Record: N59°E, 35.0 feet to estimated face.

Bearing trees recorded on Survey No. 1834 in 1961 found:

- Sugar Pine snag leaning northerly, now 8 ins. diam., brs. Record: N58½°E, 21.78 feet to estimated face. Re-measured; N57½°E, 22.55 feet to center of tree at lower blaze.
- Douglas Fir, now 19 ins. diam. with healed blazes, brs. Record: N27½°W, 5.94 feet to estimated face. Re-measured 6.0 feet to center of tree at lower blaze.
- Douglas Fir stump, now 26 ins. diam. with "BT" remaining, brs. Record: N81½°E, 17.82 feet to estimated face. Re-measured; 17.65 feet to center of stump.

Marked new trees "CS" "BT" and take measurements to center of tree at lower blaze:

- Douglas Fir, 18 ins. diam., brs. N27½°E, 46.25 feet.
- Black Oak, 6 ins. diam., brs. S72½°E, 20.0 feet.

Corner lies on 70% southerly slope approximately 60 feet east of draw course south-east.

January 9, 1989
H. Durkee, Tech.
T. Newcomb, Tech.

Verlyn Thomas
County Surveyor

V = 18°
P. -7