

## FIRST RE-ESTABLISHMENT

GCDB 300540

Quarter corner common to Sections 8 and 9, Township 36 South, Range 4 West, W.M.

Found the 1½ ins. diam. iron pipe set on Survey No. 1834 dated 1962, protruding 8 ins. above ground surface. Set a 2½ ins. diam. brass cap marked:

T36S R4W  
¼S  
8 | 9  
C S  
1990

In cement in the top of found pipe

From which:

The probable remains of the original bearing trees marked by Ives and Hyde in 1854 found:

- Half of a Ponderosa Pine burned stump brs. Record: S17°E, 73.74 feet to center of stump. Record distance; 72.60 feet to chaining notch or 73.77 feet to the center of tree.
- Madrone ring with rotted remains in the center brs. Record: N20°W, 40.6 feet to center of ring.

Bearing tree marked on Survey No. 1834 found:

- Douglas Fir, 22 ins. diam. with healed single blaze, brs. Record: S29½°W, 30.9 feet to the center of tree at base. Record; distance; 31.68 feet.

Mk new trees "CS BT" and measure to the center of tree at lower blaze;

- Douglas Fir, 6 ins. diam. brs. N36°E, 31.8 feet.
- Black Oak, 16 ins. diam. brs. S64½°E, 33.4 feet.
- Douglas Fir, 6 ins. diam. brs. N43°W, 15.5 feet.

Corner lies on a 35% East slope approximately 150 feet south of an old logging road on a blazed and painted line.

May 23, 1990  
S. Beecher, Tech.  
T. Newcomb, Tech.

Verlyn Thomas  
County Surveyor

V = 18°  
P. -80