

SPECIAL CORNER

FIRST RE-ESTABLISHMENT

GCDB 340400

Quarter corner common to Sections 16 and 21, Township 36 South, Range 4 West, W.M.

Found 18 ins. deep, a 12x12x? stone marked with cross on top. To perpetuate this location, directly over said cross, set a 1x36 ins. galvanized iron pipe in concrete, projecting 2 ins. from mound of stone with yellow plastic cap marked:

"Jackson C.S."

Take references as follows:

- A found "P-K" nail, set on Jackson County survey, in progress, located 6 ins. south of guard rail at southerly edge of asphalt surface of freeway, brs. $N7^{\circ}41'49''W$, 82.69 feet.
- Found rebars:
 - (1) $\frac{5}{8}$ ins. diam., 7 ins. deep brs. $S8^{\circ}10'E$, 25.22 feet.
 - (2) $\frac{1}{2}$ ins. diam., flush, brs. $S11^{\circ}19'E$, 32.18 feet.
- Mk a 3 ins. diam. Ash tree "X" "BT"; brs. $S48^{\circ}11'E$, 11.78 feet to center of tree at lower blaze.

Corner lies at southerly toe of freeway fill, 4 feet South of metal fence post with attached location marker.

Note: For information relative to the origin of the above noted stone and relation of other corners in Section 16, see Jackson County project file 87-17 of survey in progress.

July 30, 1987
R. Frost, Tech III
S. Beecher, Tech I

Edward McGinty
County Surveyor

P. -271