

FIRST RE-ESTABLISHMENT

GCDB 340500

Quarter corner common to Sections 9 and 16, Township 36 South, Range 4 West.

Found $\frac{3}{4}$ " iron pipe flush with the surface of the ground for corner. Replaced said pipe with a 1"x36" galvanized iron pipe, 29" in the ground with 2 $\frac{1}{2}$ " bronze cap stamped:

T. 36 S. R. 4 W.
9
 $\frac{1}{4}$ — Cor.
16
C.S.
1969

From which:

- The original bearing tree (now a 7 foot high sawed pine stump plainly scribed) bears N 44° W, 18.9 feet to the face of the lower blaze:
- The original bearing tree (now an 18" Black Oak, mostly dead and partially burned) bears S52°E, 25.4 feet to the center of the tree.

From said pipe corner, I established the following new bearing trees:

- A 14" white oak scribed "CS-BT" bears N31 $\frac{1}{2}$ °W, 11.5 feet to the face of the lower blaze;
- A 16" Black Oak, scribed "CS-BT" bears S88 $\frac{3}{4}$ °E. 64.5 feet to the face of the upper blaze.

August 11, 1969
F. Roberts, Deputy County Surveyor
O. Blankenship