

FIRST RE-ESTABLISHMENT

GCDB 340700

Quarter corner to Section 33, Township 35 South, Range 4 West and Section 4, Township 36 South, Range 4 West.

Set a 1"x36" galvanized iron pipe with top 2" above the ground surface for corner from which:

- The original witness tree (Now a 14" Black Oak) with 'BT' scribe legible bears S28½°W, 15.2 feet;
- The original witness tree (Now a 14" Black Oak) with 2 old axe faces, but scribing rotted away bears N30° E, 44.2 feet;

I scribe new trees as follows:

- A 12" Douglas Fir "CS-BT" which bears S7½°W, 17.1 feet.
- A 14" Black Oak "CS-BT" which bears N56¼°E, 68.2 feet.

July 15, 1957
M. E. Boyden
K. D. Weaver

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 340700

Quarter corner common to Section 4, Township 36 South, Range 4 West and Section 33, Township 35 South, Range 4 West, W.M.

Found the 1 ins. diam. galvanized iron pipe set on the first re-establishment page 15, date 1953.

Set a 2 ½ ins. diam. brass cap marked:

R4W
33
¼S —
4
T36S
C.S.
1987

In cement in top of found pipe.

Original bearing tree marked by Ives and Hyde in 1854 found:

- Root hole and down Oak with fragments of scribing visible in opened blaze, brs. Record: S31½°W, 15.2 feet to estimated position of scribed face.

Bearing trees marked on first re-establishment found:

- Douglas Fir 17 ins. diam. with healed blazes, brs. Record: S07½°W, 17.1 feet to estimated face. Re-measure 17.57 feet to center of tree at base.
- Black Oak, broken-off, now a 24 ins. diam. stump shell, brs. Record: N56¼°E, 68.2 feet to estimated face position.

Mk a new tree "CS" "BT" and measure to center of tree at base:

- Douglas Fir, 16 ins. diam., brs. S84°W, 40.37 feet.

Corner lies on 57% Southeast slope approximately 500 feet East of a large steel 'I' beam with wood decking bridge being built across Evans Creek at a point 400 feet upstream from concrete dam.

August 13, 1987
S. Beecher, Tech I
R. Frost, Tech III

Edward McGinty
County Surveyor

V = 17¾°
P.-297