

FIRST RE-ESTABLISHMENT

GCDB 400240

Quarter corner common to Sections 27 and 28, Township 36 South, Range 4 West, W.M.

Found 4 ins. deep, the 1 ins. diam. iron pipe with attached 1¼ ins. diam. pipe coupler set by proportionate method for the corner on Survey No. 1501 in 1960. To perpetuate this location, in the top of the above noted monument, set in cement a 2½ ins. diam. brass cap marked:

T36S R4W
JACKSON
*
COUNTY
1982

From which,

- An apparent reference tree (unrecorded); a White Oak, now 16 ins. diam. with healed double blazes, brs. S58°20'W, 55.6 feet to center.

Mk new trees "CS" "BT" and take measurements to center of trees at lower blaze:

- Ponderosa Pine, 8 ins. diam., brs. N6°05'E, 59.1 feet.
- White Oak, 14 ins. diam., brs. N87°15'W, 53.3 feet.

Corner lies about 40 feet S35°E of the intersection of farm roads C. north and easterly-westerly.

June 22, 1982
E. McGinty
R. Frost

Edward McGinty
County Surveyor

V = 18°
P.-90

SEE NEXT PAGE FOR ADDENDUM

ADDENDUM:
GCDB 400240

Found brass cap broken off with pipe bent over. Replaced damaged monument with a 1x36 ins. diam. galvanized iron pipe set 30 ins. in the ground with a 2½ ins. diam. brass cap marked:

T36S R4W
¼S
28 * 27
CS
1994

June 7, 1994
T. Newcomb, Tech.
J. Burgess, Tech.