

FIRST RE-ESTABLISHMENT

GCDB 400460

North 1/16 corner between Sections 15 and 16, Township 36 South, Range 4 West, W.M.

Set a $\frac{3}{4}$ x 30 ins. galvanized iron pipe 30 ins. in the ground for corner from which:

- The SW corner of the concrete foundation of a stone fireplace brs. N77°E, 36.65 feet.
- The NE corner of a concrete foundation at the NE corner of a residence brs. S24 $\frac{3}{4}$ °E, 83.92 feet.

August 5, 1956

M. E. Boyden

L. D. Pinkham

C. L. Birk

NOTE: For more detailed information on bearings and distances see Recorded Survey No. 915.

SEE NEXT PAGE FOR SECOND RE-ESTABLISHMENT

SECOND RE-ESTABLISHMENT

GCDB 400460

North sixteenth corner common to Sections 15 and 16, Township 36 South, Range 4 West, W.M.

Found 4 ins. deep, the $\frac{3}{4}$ ins. diam. iron pipe, set on first (re)establishment in 1956. In the top of found pipe, set a yellow plastic cap marked "Jackson C.S." from which, references reported in 1956 found:

- The Northeast corner of the concrete foundation of residence 947 Pine St., brs. S24°57'E, 84.19 feet. Record; S24 $\frac{3}{4}$ °E, 83.92 feet.
- The Southwest corner of concrete foundation of stone, fireplace chimney of residence 1003 Pine St., brs. N76°48'E, 36.85 feet. Record; N77°E, 36.65 feet.

To perpetuate this location, take additional references as follows:

- A found P-K nail in asphalt, reported in the field notes of Survey No. 10871, dated 1987, brs. S59°31'48"E, 161.82 feet.
- Set a $\frac{3}{4}$ x 24 ins. rebar, 2 ins. deep, with a yellow plastic cap marked "Jackson C.S.", about 3 $\frac{1}{2}$ feet South of a 13 ins. diam. Black Oak, brs. N56°42'E, 19.80 feet.

Corner lies about 14 feet S11°E of middle of 42 ins. diam. Ponderosa Pine.

July 8, 1987
R. Frost, Tech III
S. Beecher, Tech I

Edward McGinty
County Surveyor

P.-247